

# **OMB 301**

# PROGRAMMABLE BARGRAPH

DC VOLTMETER/AMMETER
PROCESS MONITOR
OHMMETER
THERMOMETER FOR PT 100/500/1 000
THERMOMETER FOR NI 1 000/2 226/10 000
THERMOMETER FOR THERMOCOUPLES
DISPLAY INSTRUMENT FOR LIN.
POTENTIOMETERS



1

#### SAFETY INSTRUCTIONS

Please, read the enclosed safety instructions carefully and observe them!

These instruments should be safeguarded by isolated or common fuses (breakers)!

For safety information the EN 61 010-1 + A2 standard must be observed.

This instrument is not explosion-safe!

# **TECHNICAL DATA**

Measuring instruments of the OMB 301 series conform to European regulation 89/336/EWG.

They are up to the following European standards: EN 55 022, class B

EN 61000-4-2, -4, -5, -6, -8, -9, -10, -11

The instruments are applicable for unlimited use in agricultural and industrial areas.

### CONNECTION

Power supply from the main line has to be isolated from the measuring leads.



# ORBIT MERRET, spol. s r.o.

Vodnanska 675/30 198 00 Prague 9 Czech Republic

Tel: +420 - 281 040 200 Fax: +420 - 281 040 299 e-mail: orbit@merret.cz www.orbit.merret.cz







# 1. CONTENTS

1.			
2.		cription	
3.	Connection		. 6
4.	Instrument setti	ng	. 8
	Setting the dea	imal point and the minus sian	. 9
	Access into the	e configuration mode	. 9
		through minimum instrument setting	
		IENU.	
		Limits - entering the values.	
		Analog output	
		Data output	
		Display brightness	
		Tare resetting.	
		· ·	
		uration MENU	
	4.3.1	4.3.1.1 Limits.	
		4.3.1.1 Limits.  4.3.1.2 Analog output	
		4.3.1.3 Data output	
		4.3.1.4 Display brightness	
		4.3.1.5 Tare resetting	
	132	Configuration Mode - CONFIG	
	4.5.2	4.3.2.1.1 Setting Access into the limits Menu	
		4.3.2.1.2 Setting the relay function	
		4.3.2.2.1 Setting Access into the analog output menu.	
		4.3.2.2.2 Setting the type of the analog output	
		4.3.2.3 Setting Access into the data output menu	
		4.3.2.4 Setting Access into the menu of brightness setting	21
		4.3.2.5 Setting Access into the menu of tare resetting.	21
	4.3.3	Configuration Mode - INPUT	22
		4.3.3.1 Projection on the display	23
		Setting for linear potentiometer.	23
		4.3.3.2 Shifting the beginning of the range	23
		4.3.3.3 Compensation of 2-wire conduct OHM RTD	24
		4.3.3.4 Setting the type of connection.	24
		4.3.3.5 Setting the cold junction	24
		4.3.3.6 Setting the Method of measurement of the cold junction	25
		4.3.3.7 Digital filter	2.5
		4.3.3.8 Setting the measuring range DC PM RTD OHM T/C	26
		4.3.3.9. Setting the measuring rate	27
		4.3.3.9 Setting the measuring rate. 4.3.3.10 Setting the description of measuring Units DC PM DU OHM.	27
	434	Configuration Mode - BARGR.	28
	4.0.4	4.3.4.1 Bargraph projection display	
		4.3.4.2 Setting the projection mode.	
		4.3.4.3 Setting the LED colours	
5	Configuration I	nput	
6.		ls	
	,		
7.		s. of the cold junction	
8.	Data protocol .		33
9.	Error statement	S	34
10		ensions and instal.	
		crisions and misra.	
		conformity	
13.	Certificate of g	parantee	39

# 2. INSTRUMENT DESCRIPTION

#### DESCRIPTION

The OMB 301 model line are horizontal bargraphs with tri-color 30 LED with auxiliary 6-digit display, manufactured in the following alternatives:

OMB 301DC DC voltmeter/ammeter

OMB 301 PWR \*Nets analyser - AC voltmeter/ammeter/wattmeter

OMB 301 PM Process monitor

OMB 301RTD Thermometer for Pt 100/500/1 000, Ni 1 000/2 226/10 000

OMB 301T/C Thermometer for thermocouples

OMB 301 DU Display instrument for linear potentiometers

OMB 301 OHM Ohmmeter

The instruments are based on an 8-bit microcontroller with precise A/D converter, that secures high accuracy, stability and easy operation of the instrument.

# Programmable projection of the display

Calibration projection for the beginning and the end of the input range

setting the type of input

Projection 30 LED with adjustable color of projection (red - green - orange)

6-digit auxiliary display

# Digital filters

Radius of insensitiveness adjustable in process units

#### Mathematic functions

Tare assigned to reset the display in case of non-zero input signal

# External control

Hold display/instrument blocking

Lock locking the control keys or the access into Configuration menu

<sup>\*</sup> These instruments have separate Instructions for use

### OPERATION

The instrument is set and controlled by five control keys located on the front panel. All programmable settings of the instrument are realised in two adjusting modes:

Configuration menu (hereinafter referred to as "CM") is protected by an optional numeric code and containis

complete instrument setting

User menu may contain arbitrary programming setting defined in CM with another selective restriction

(see, change)

All programmable parameters are stored in the EEPROM memory (they hold even after the instrument is switched off).

The measured units may be projected on the display.

### **EXTENSION**

Excitation is suitable for feeding of sensors and converters. It has a galvanic isolation with continuously adjustable value in the range of 2...24 VDC.

**Dual comparator** is designed to monitor two limit values with relay output. Limits have adjustable hysteresis as well as selectable delay of the switch-on. Reaching the preset limits is signalled by LED and at the same time by the switch-on of the relevant relay.


**Data outputs** are for their rate and accuracy suitable for transmission of measured data for further projection or directly into the control systems. We offer isolated RS232 and RS485 with the ASCII protocols.

**Analog outputs** will find their place in applications where further evaluating or processing of measured data in external devices is required. We offer universal analog output with the option of selection of the output type - voltage/current. The analog output value corresponds with the displayed data and its type and range are selectable in the programming mode.


# 3. CONNECTION

The supply lead for feeding the instrument should not be in the proximity of low-potential signals.

Contactors, motors with larger input and other efficient elements should not be in the proximity of the instrument. The lead into the instrument input (the measured quantity) should be in sufficient distance from all power leads and appliances. Provided this cannot be secured, it is necessary to use shielded leads with connection to ground. The instruments are tested in compliance with standards for use in industrial area, yet, we recommend to abide by the above mentioned principles.



- Grounding on terminal "E" must be connected at all times
- In RTD input with 2-or 3-wire connection it is necessary to link the unconnected inputs (13/14 and 15/16 or 15/16)
- Relay parameters specified in the technical data apply for resistance load. Upon connection of the induction load we recommend to fit the leads to relay 1 A with a fuse for maximum load protection.




#### MEASURING RANGES

L2

Туре	Input 1 (I)	Input 2 (U)
OMB 301 DC - U	060/150/300 mV	04/40/400 V
OMB 301 DC - I	01/5 A	0400 mA
OMB 301 PM	0/420 mA	02/5/10 V
OMB 301 OHM	00,4/4/40 kOhm	5105 Ohm, (upon request 0100 kOhm)

# 4. INSTRUMENT SETTING

The instrument is set and controlled by 5 control keys located on the front panel. By means of these control keys it is possible to browse through the operting program, to select and set the required values.



### **CONFIGURATION MODE**

- · designated for professional service and maintenance
- · complete instrument setting
- · access is password protected
- authorization for "User mode"

#### **USER MODE**

- · designated for instrument service
- may contain setting the limits, analog and data output and brightness, with restriction as per the setting in "Configuration mode"

# SYMBOLS USED IN THE INSTRUCTIONS

DC PM DU OHM RTD T/C

Indicates the setting for given type of instrument

#### CONTROL KEYS FUNCTIONS

<b>©</b>	8	0	•	•	
MENU	ENTER	LEFT	DOWN	UP	
Measuring mode					
menu access	tare	tare projection			
Moving around in the	e menu				
exit the menu without saving	move to next level	back to previous level		move to enxt item	
Setting/selecting - items					
cancel setting without saving	confirm selected item		move down	move up	
Setting - numbers					
cancel setting without saving	cancel selected number	move to higher decade	change of current figure - down -	change of current figure - up -	

### SETTING THE DECIMAL POINT AND THE MINUS SIGN

#### DECIMAL POINT

Its selection in calibration modes, upon modification of the number to be adjusted is performed by the control key with transition behind the highest decade, when the decimal point starts flashing. Positioning is performed by ...

Decimal point is set only in the item "Input - MIN"

#### MINUS SIGN


It is adjustable upon the shift of the decimal point accross all decades, back to the first one, at which the minus sign will light up. The setting is repeated, i.e. 1x around only positioning of the decimal point and upon next passage accross all decades the minus sign lights up and the decimal point is placed.



#### Setting

- ⇒ "Calibration mode" ⇒ Input ⇒ Minimum
- ⇒ InPUL ⇒ N In
- ⇒ after transition behind the highest decade **(** the decimal point starts flashing
- ⇒ by pressing ♠ or ♠ you will place the decimal point and confirm it by ♠
- In the MIN item the setting of the decimal point is determining for the entire instrument

# **ACCESS INTO THE CONFIGURATION MODE**



The code is always preset from manufacture to 0000. In case of loss of access password it is possible to use universal access code "8177"

#### **GUIDE THROUGH MINIMUM INSTRUMENT SETTING** 4.1

Access into the "Configuration menu"



Entering the introductory PRSS access password

Standard manufacture 0000 setting of the access password

type of input



# DC Input

- ammeter and voltmeter are two independent

# PM Input

- setting the measuring range

### RTD Input

- setting the type of sensor

- Pt 3850 ppm/°C EU, standard Pt 3920 ppm/°C US, upon request Ni 5000 ppm/°C standard Ni 6180 ppm/°C upon request

# **OHM Input**

- setting the measuring range

5...105 Ohm - 100 R (100 K 0...100 kOhm), upon request

400 R 0...400 Ohm 4 K 0...4 kOhm 40 K 0...40 kOhm

#### T/C Input


CUC

- setting the type of thermocoupler


- selling the type of t	nemiocoopiei
- B	type B
R	type R
S	type S
T	type T
E	type E
J	type J
K	type K
N	type N
CJC	the temperature of th
	cold junction

			3	.8, 7
2	Selec	tion of t	he mea	s. range/
<b></b>				
<b>⊕ ⊕ →</b>	⊖→			<b>←0</b>
0	n PRSS		DC-V	DC - A
ŧ	NEnU	ΠIn	0-4 u	400 nR
	COnf IG	ПЯН.	0-40 J	! R
	InPUL	FILEEr	0-400 u	5 R
	bArGr.	FALE	0-60 nu	
		rERdr5	0-150 n	
		EHR-5.	0-300 n	
			PM	ОНМ
			0-2 ∪	100 r
			0-5 u	400 r
			0-10 u	4 +
			0-20-8	40 F
			4-20n8	
			RTD - Pt	T/C
			PE 100	ь
			PE 500	
			PE 1000	5
			RTD - NI	٤
			n : 1000	ε
			n 12226	J
			n i 10F	F
4				n
- 1				


# Setting projection on the display



# Setting the projection mode



# Setting the LED colours



# InPUL

### Setting the input parameters

Type of input	Displayed items of the menu
DC	MIN, MAX
PM	MIN, MAX
DU	MIN, MAX
ОНМ	MIN, MAX, *LEADS
RTD	*LEADS, CONNEC.
T/C	CJC, COMP.TC

<sup>\*</sup> only for 2-wire

# noa

Setting the bargraph projection mode

- to be set in the range of 0...6
- bargraph is off
- single-colour column, colour is set in entry Col. OR
- see 1, auxiliary display is off in the measuring mode
- single-colour column with point identification of the limits, colour is set in the entry Col. OR
- (red or green colour only) see 3, auxiliary display is off in the
- measuring mode three-colour column - the colour is

determined by th limit value no limit colour is set in the entry

Col. OR colour is set in the entry one active limit

Col. 1R two active limits

colour is set in the entry Col. 2R

see 5, auxiliary display is off in the measuring mode

# COL. Or.

Setting the bargraph LED colours

- setting the colour coloumn according to options in regime "MODE"

RED red colour GREEN green colour ORANGE orange colour

# 4.2 USER MENU

- · designated for instrument service
- may contain setting the limits, analog/data output and brightness, with restriction as per the setting in "Configuration mode"

23.6



Setting limits, Setting the hysteresis and analog output delay


Setting limits, Setting the Output output delay

Setting limits, Setting the Ada Setting the display brightness


Tare resetting Instrument setting

Projection of items and their accessibility depends on the setting of access rights in the "Configuration menu"

# 4.2.1 LIMITS - ENTERING THE VALUES



Adjustable authorization of access into items, see page 19



Setting hysteresis only in


- in 1/10 of the display range

**HYS I** 

Setting the delay of relay activation

- in the range of 0...99,9 s

# 4.2.2 ANALOG OUTPUT



- Adjustable authorization of access nito items, see page 20
- Analog and data outputs may not be fitted simultaneously in this instrument

# Setting the analog output range

 analog output is isolated and its value corresponds with the displayed data. It is fully programmable, i.e. it allows to assign the AO limit points to any two arbitrary points of the entire measuring range

Assigning the displayed value to the beginning of the analog output range

- range of the setting is -999...3999


80-N8H

Assigning the displayed value to the end of the

analog output range

- range of the setting is -999...3999

# 4.2.3 DATA OUTPUT



Adjustable authorization of access into items, see page 21

# Setting the data output parameters

*⊾RUd* Set

Setting the transmission rate (baud)


 setting in the range of 150/300/600/1200/ 2400/4800/9600/19200/38400/57600/ 115200 Baud

Rdr

Setting the instrument address

- setting in the range of 0...31
- manufacture setting 00 DIF

# 4.2.4 DISPLAY BRIGHTNESS




# Setting the display brightness

- by selecting the display brightness we may properly react to light conditions in place of location of the instrument
- brightness in the programming menu is always 80 %

Adjustable authorization of access into items, see page 21

# 4.2.5 TARE RESETTING



Adjustable authorization of access into items, see page 21


ELr.ERr.

Tare resetting


 after confirmation the tare will be reset to zero and the LED "T" will turn off

# 4.3 CONFIGURATION MENU

- designated for professional service and maintenance
- · complete instrument setting
- the access is protected by a password or a jumper on the input connector
- authorization for "User mode"



# 4.3.1 CONFIGURATION MODE - MENU



The basic instrument parameters are adjusted in this menu

LINIES

Setting the limit values for status evaluation

Setting the analog output range


ARER

Setting the data output parameters

Bet IGHE.

Setting the display brightness

# 4.3.1.1 LIMITS



The procedure of setting the limit 2 is identical as for limit 1

# Entering the limit values for status evaluation

Tare resetting

CLr.ERr.

L Iff 2 Setting for Limit 1

LINIEI Setting the limit for relay switch-on


- in full range of the display

Setting hysteresis only in (+) values


- in 1/10 of the display range

Setting the delay for relay activation

- in the range of 0...99,9 s



### 4.3.1.2 ANALOG OUTPUT



Setting the analog output range

 analog output is isolated and its value corresponds with the displayed data. It is fully programmable. i.e. it allows to assign the AO limit points toany two arbitrary points of the entire measuring range

Assigning the displayed value to the beginning of

the AO range


- range of the setting is -999...3999

Assigning the displayed value to the end of the AO range

- range of the setting is -999...3999

Analog and data outputs may not be fitted simultaneously in this instrument

### 4.3.1.3 DATA OUTPUT



Setting the data output

Setting the transmission rate (baud)

 setting in the range of 150/300/600/1200/ 2400/4800/9600/19200/38400/57600/ 115200 Baud


Setting the instrument address


- setting in the range of 0...31

- manufacture setting 00 DEF

Analog and data outputs may not be fitted simultaneously in this instrument

# 4.3.1.4 DISPLAY BRIGHTNESS






- by selectiving the display brightness we may react properly to light conditions in place of location of the instrument
- brightness in the programming menu is always 100%

10',	Display brightness = 10 %
201	Display brightness = 20 %
40',	Display brightness = 40 %

Display brightness = 80%

Display brightness = 100%


# 4.3.1.5 TARE RESETTING



# ELCERC Tare resetting

 after confirmation the tare will be reset to zero and the LED "T" will turn off

# 4.3.2 CONFIGURATION MODE - CONFIG



The configuration code may consist of up to 6 numbers, which determine the operational setting of the instrument. Individual meaning and setting of the numbers are described in relevant chapters of the configuration mode.

Setting the access rights to individual options for "User mode"

 one of the prime merits of this function is the feasibility to assign authorization for access and modification of parameters in individual steps of the "User mode". This setting will facilitate the instrument service staff easy operation and prevent unauthorized interference into the setting of vital functions.

Configuration of the access into "Limits" menu and relay function

Configuration of the access into "AO" menu and


selection of the AO type

Configuration of the access into "RS" menu

Configuration of the access into "Brightness" menu

Configuration of the access into "Tare" menu

### 4.3.2.1.1 SETTING ACCESS INTO THE LIMITS MENU



Configuration of the access into "Limits" menu and relay function


Setting the access rights

- selection of the access rights for "User mode"

A - Limit 1, B - Limit 2

Rights	Limits	Hyst.	Time	BA
Prohibited	×	×	×	0
	✓	×	×	1
Projection	✓	✓	×	2
	✓	✓	✓	3
	✓	×	×	4
Change of setting	✓	✓	×	5
	✓	✓	✓	6

# 4.3.2.1.2 SETTING THE RELAY FUNCTION




# FEE. L Relay configuration

A - Limit 1 B - Limit 2

Relay fuunction		ВА
D.I.	switch-on	0
Relay	switch-off	1

# 4.3.2.2.1 SETTING ACCESS INTO THE ANALOG OUTPUT MENU




# Configuration of the access into "AO" menu and selection of the AO type

NEDU. 80 Setting the access rights

- selection of the access rights for "User mode"

Rigts	Α
Prohibited	0
Projection	1
Change of setting	2


# 4.3.2.2.2 SETTING THE TYPE OF THE ANALOG OUTPUT



# Setting the type of the analog output

upon error statement the value on the output is < 3,6 mA</li>

# 4.3.2.3 SETTING ACCESS INTO THE DATA OUTPUT MENU






# Setting the access rights

- selection of the access rights for the "User

Rights	А
Prohibited	0
Projection	1
Change of setting	2

# 4.3.2.4 SETTING ACCESS INTO THE MENU OF BRIGHTNESS SETTING






Configuration of the access into "Brightness"

- selection of access rights for the "User mode"

Rights	
Prohibited	0
Projection	1
Change of setting	2

### 4.3.2.5 SETTING ACCESS INTO THE MENU OF TARE RESETTING




COn.EAr.

Configuration of the access into tare resetting

- selection of access rights for the "User mode"

Rights						
Prohibited, the function is off						
Projection	1					
Resetting to zero permitted	2					

# 4.3.3 CONFIGURATION MODE - INPUT



InPUL	Setting the input parameters
n In	Setting display projection for minimum value of the input
กรห signal	Setting display projection for maximum value of the input
FILEEr	Setting the digital filter
OFFSEE	Shift of the beginning of the measuring range
LEAdS	Compensation of 2-wire conduct
EYPE	Setting the instrument meas. range and connection <b>6</b>
EOnnEE.	Setting the type of input connection
rEAdrS	Setting the instrument measuring rate 8
CHR-S.	Setting the projection of measuring units
נטנ	Setting the temperature of the cold junction ©
CONP.EC	Method of measurement of the cold junction

Input type	Setting opt	Setting options										
DC	023	6	8 9									
PM	023	6	8 9									
DU	023		8 9									
ОНМ	023	(5)	8 9									
RTD	3 4	<b>\$ 6 7</b>	8									
T/C.	3	6	8	0 ⊙								

# 

4.3.3.1

DC PM DU OHM

Setting display projection for minimum value of the

input sianal

- range of the setting is -999...3999
- positioning of the decimal point in this item is determining for the entire instrument

ПЯН

Setting display projection for maximum value of the input

signal

- range of the setting is -999...3999
- Setting of the decimal point in the MIN item is determining for the entire instrument


#### SETTING FOR LINEAR POTENTIOMETER

rER875

CHRES

PROJECTION ON THE DISPLAY

DU




Call to place the potentiometer traveller into

initial position

- in the MIN and MAX items enter the required projection and confirm by pressing "Enter"
- before confirming the sign "MEAS?" by "Enter" the potentiometer traveller has to be positioned and stabilized at the beginning of the measuring range
- the "MEASUR" sign indicates automatic calibration of the measuring range, the potentiometer traveller has to be at rest
- Calibration for second position is identical with setting of the beginning

#### 4.3.3.2 SHIFTING THE BEGINNING OF THE RANGE

RTD



Shifting the beginning of the range

- in cases when it is necessary to shift the beginning of the range by certain value, e.g. when sensor is used in a measuring head
- entered directly in Ohm

4.3.3.3

# **COMPENSATION OF 2-WIRE CONDUCT** ( $\Theta \rightarrow$ 0 2855 NEnU OFFSEL 9ES2. CONFIG LERdS InPUL FILEEr EUPE barGr. COnnEC

rERd75

Compensation of 2-wire conduct

онм RTD

- for measurement accuracy it is necessary to perform compensation of the conduct always in case of 2-wire connection
- entered directly in Ohm


I FRAS

- prior to confirmation of the displayed challenge "YES?" it is necessary to substitute the sensor at the end of the conduct by a short circuit
- preset from manufacture to "O"

The items are visible at all times but the active only upon set 2-wire connection

#### 4.3.3.4 SETTING THE TYPE OF CONNECTION

RTD



Setting the type of ŁYPE connection


2-wire input connection 2-01-8

3-wire input connection 3-01-E

4-wire input connection 4-111cF

#### SETTING THE COLD JUNCTION 4.3.3.5


T/C




Setting the temperature בטב of the cold junction

- range of 0...98 °C with compensation box
- 99 °C without compensation box, with/ without reference thermocouple, temperature of the cold junction is measured at the input brackets of the instrument
- Method and procedure of the setting of the cold junctions are described in a separate chapter on page 32


# 4.3.3.6 SETTING THE METHOD OF MEASUREMENT OF THE COLD JUNCTION





Method and procedure of setting of the cold junctions are described in a separate chapter on page 32


# 4.3.3.7 DIGITAL FILTER



# FILEEr

# Setting the digital filter

- use of the digital filter will find its place in applications where the change of projection on the display (by given value) interferes or is not substantial in the measuring regime
- it is entered directly in digits and is valid symetrically



#### 4.3.3.8 SETTING THE MEASURING RANGE DC PM RTD LYPE 0 $\Theta \rightarrow$ -O 0 n PRSS DC-V DC - A DC Input NEnU n In 0-40 400 nR CONFIG пан 0-40 0 18 InPUL FILEEr 0-400 J 5 R barGr. EYPE 0-60-0 rERd75 0-150 n CHRES 0-300 n ОНМ РМ 0-20 100 -PM Input 0-50 400 -4 + 0-10 u 0-20nR 4N F 4-20 nA 4...20 mA 4-20nR RTD - Pt T/C RTD Input PE 100 ь - setting the type of sensor PE 500 r 5 PE 1000 Ŀ RTD - NI Ε n : 1000 **OHM Input** n 12228 J setting the measuring range n : 10+ F n CUC

Upon a change of the range check also the necessary jumper settings (page 30) and connection of given input (page 7)

Setting the measuring range of the instrument

онм T/C

- ammeter and voltmeter are two independent

instruments	
0-4 v	04 V
0-40 v	040 V
0-400 v	0400 V
0-60 n	060 mV
0-150 n	0150 mV
0-300 n	0300 mV
400 nA	040 mA
1 A	01 A
5 A	05 A

- setting the measuring range

0-2 v	02 V
0-5 v	05 V
0-10 v	010 V
0-20 nA	020 mA
120 -1	4 20 4

	seming me type of	5011501
-	Pt 100	Pt 100
	Pt 500	Pt 500
	Pt 1000	Pt 1 000
-	Ni 1000	Ni 1 000
	Ni 2226	Ni 2 226
	Ni 10 k	Ni 10 000


-	sening me measurii	ig range
-	100 r	5105 Ohm
	(100 K	0100 kOhm), upon
	request	
	400 r	0400 Ohm
	4 k	04 kOhm
	40 k	040 kOhm

# T/C Input

- setting the type of thermocouple

	seming me type of it	icimocoopic
-	В	type B
	R	type R
	S	type S
	T	type T
	E	type E
	J	type J
	K	type K
	N	type N
	CJC	the temperature of the cold junction

### 4.3.3.9 SETTING THE MEASURING RATE



⊕ →


0 2855

COnF 10

InPUL

barGr.

ПЕПИ



 setting the measuring rate is associated with the rate of response to evaluation of the relay status and analog output

Rate - 1,3 measurements/s

...........

Rate - 2,5 measurements/s

Sar's Rate - 5 measurements/s

10 n r'5 Rate - 10 measurements/s

Rate - 20 measurements/s

Rate - 40 measurements/s

# 4.3.3.10 SETTING THE DESCRIPTION OF MEASURING UNITS

- 0

ΠIn

пан

FILLER

rERdrS

CHARS

LYPE



# EHR-5 display

# Setting projection of measuring units on the

 the instrument allows to add two descriptive characters to the classic numeric formats (at the expense of the number of displayed places). The setting is performed by means of a shifted ASCII code. Upon setting the first two places display the entered characters and the last two places the code of the relevant symbol from 0 to 95.


Description is cancelled by entering characters 00


 instruments with the input for temperature measurement display as a stadard °C

Ö


Table of symbols is on page 31

# 4.3.4 CONFIGURATION MODE - BARGR.





# 4.3.4.1 BARGRAPH PROJECTION DISPLAY



n In

Setting the beginning of the bargraph range


 in this programming step we may set the display value which correspons with the minimum bargraph projection

Setting the end of the bargraph range

 in this programming step we may set the display value which correspons with the miaximum bargraph projection

If Min > Max is entered, then the projection on the bargraph is becoming shorter with the increasing display value

### 4.3.4.2 SETTING THE PROJECTION MODE



Limits are accessible in the "Configuration menu" even if the relays in the instrument are not fitted



# Setting the bargraph projection mode

- to be set in the range of 0...6
- 0 bargraph is off
- 1 single-colour column, colour is set in entry Col. OR
- 2 see 1, auxiliary display is off in the measuring mode
- 3 single-colour column with point identification of the limits, colour is set in the entry Col. OR (red or green colour only)
- 4 see 3, auxiliary display is off in the measuring mode
- three-colour column the colour is determined by th limit value


no limit colour is set in the entry
Col. OR

one active limit colour is set in the entry Col. 1 R

two active limits colour is set in the entry Col. 2R

6 see 5, auxiliary display is off in the measuring mode

# 4.3.4.3 SETTING THE LED COLOURS





Setting the bargraph LED colours

setting the colour coloumn according to options in regime "MOdE"

RED red colour GREEN green colour ORANGE. orange colour



Setting in menu "Col. 1r" and "Col. 2r." is the same

# 5. CONFIGURATION INPUT

Jumpers are accessible after the instrument is opened

1	INPUT	"2" (DC)	60 mV	150 mV	300 m\		
DD J7	J7	Not	×	✓	$\checkmark$		
<u>□</u> □ J8		Yes	$\checkmark$	×	×		
	18	Not	×	×	x		
		Yes	×	<b>Y</b>	¥		

<b>□</b> J1	Jī	Not	✓	x
		Yes	×	✓

Hold

Lock


FUNKTIONS







INPUT		OHM - Input 1
J5	5 - 6	0400 Ohm
	3 - 4	04 kOhm
	1 - 2	040 kOhm



For every jumper setting disconnect the instrument from the mains

# 6. TABLE OF SYMBOLS


The instrument allows to add two descriptive characters to the classic numeric formats (at the expense of the number of displayed places). The setting is performed by means of a shifted ASCII code. Upon modification the first two places display the entered characters and the last two places the code of the relevant symbol from 0 to 95. Numeric value of given character equals the sum of the numbers on both axes of the table.

Description is cancelled by entering characters with code 00

	0	1	2	3	4	5	6	7		0	1	2	3	4	5	6	7
0		I.	"	В	5	',	2	,	0		ļ.	"	#	\$	%	&	1
8	Ε	J	Н	4	,	-		رم	8	(	)	*	+	,	-		/
16	0	1	2	3	ч	5	Б	7	16	0	1	2	3	4	5	6	7
24	8	9	Ξ	1.	c	Ξ	5	₽.	24	8	9	:	;	<	=	>	Ś
32	3	R	Ь	٤	б	Ε	F	Б	32	@	Α	В	С	D	Е	F	G
40	н	1	J	F	L	Π	Ω	0	40	Н	1	J	Κ	L	Μ	Ν	0
48	ρ	9	_	5	Ŀ	U	U	U	48	Р	Q	R	S	Τ	U	٧	W
56	н	У	2	٤	4	3	n	-	56	Χ	Υ	Z	[	\	]	^	_
64	,	R	Ь	c	б	Ε	F	Б	64	,	а	b	С	d	е	f	g
72	h	,	ر	۲	1	О	n	0	72	h	i	i	k	1	m	n	0
80	ρ	9	_	5	Ŀ	U	u	U	80	р	q	r	s	t	U	٧	W
88	н	У	2	⊣	1	۲	0		88	х	У	z	{	Ι	}	~	

# 7. METHOD OF MEAS. OF THE COLD JUNCTION

An instrument with input for temperature measurement with thermocouple allows for setting of two types of measurement of the cold junction.



Reference thermocouple

#### WITH REFERENCE THERMOCOUPLE

- a reference thermocouple may be located in the same place as the measuring instrument or in place with stable temperature/compensation box
- when measuring with reference thermocouple set EDTPLE in the instrument menu to E. 4E5
- $\blacksquare$  when using a thermostat (a compensation box or environment with constant temperature) set  $\mathcal{EJL}$ . In the instrument menu to its temperature
- if the reference thermocouple is located in the same environment as the measuring instrument then set £J£ in the instrument menu to number 99. Based on this selection the measurement of the surrounding temperature is performed by a sensor located in the instrument terminal board.

#### WITHOUT REFERENCE THERMOCOUPLE

- innacuracy originating from the creation of dissimilar thermocouples on the transition point terminal-conductor of the thermocouple is not compensated for in the instrument
- when measuring without reference thermocouple set £000€£. in the instrument menu to £. a0₺
- when measuring temperature without reference thermocouple the error in measured data maybe even 10°C

# 8. DATA PROTOCOL

The instruments communicate via serial line RS232 or RS485. For communication they use the ASCII protocol. The communication is running in the following format:

ASCII: 8 bit, no parity, one stop bit

Transmission rate is adjustable in the instrument menu and depends on the used control processor. The instrument address is set in the instrument menu in the range of 0...31. Manufacture setting always presets the ASCII protocol, rate of 9600 Baud, address 00. Type of line used - RS232 / RS485 - is determined by exchangeable card automatically identified by the instrument.

# **COMMANDS FOR INSTRUMENT OPERATION**

The commands are described in the description which can be found at www.orbit.merret.cz/rs.

The command consists of a couple number-letter, where the letter size is of importance.

Symbol	Meaning	Symbol	Meaning
<b>(1)</b>	Send unit value	G	Complete number
<b>(3</b>	Set unit value	O	Selection = complete number
0	Perform relevant action	0	Decimal number
		0	Text - printable ASCII characters
		0	Intel HEX format

### **DETAIL DESCRIPTION OF COMMUNICATION VIA SERIAL LINE**

Activity	Туре	Pro	tocol	Data transferred																			
D . 1: (DC)	232	1	ASCII	#	А	А	<cr></cr>																
Data solicitation (PC)	485	1	ASCII	#	Α	Α	<cr></cr>																
Data transfer	232	ASCII		>	D	D	D	D	D	D	D	(D)	(D)	(D)	<cr></cr>								
(Instrument)	485	1	ASCII	>	D	D	D	D	D	D	D	(D)	(D)	(D)	<cr></cr>								
Command transfer	232	1	ASCII	#	Α	Α	N	Р	D	D	D	D	(D)	(D)	(D)	<cr></cr>							
(Instrument)	485	1	ASCII	#	Α	Α	N	Р	D	D	D	D	(D)	(D)	(D)	<cr></cr>							
	000	232	ok	. !	Α	Α	<cr></cr>																
Command confirma-	232	≙	bad	ś	А	Α	<cr></cr>																
tion (Instrument)	485	ASC	ok	!	А	Α	<cr></cr>																
		485	485	485	485	485	485	485	485	₽	bad	ŝ	Α	Α	<cr></cr>								

# 9. ERROR STATEMENTS


ERROR	REASON	ELIMINATION					
E. Und.	range underflow (A/D converter)	change the input signal value or change display projection					
E. Ou Er.	range overflow (A/D converter)	change the input signal value or change display projection					
E. NRE	mathematic error, range of projection is out of display	change the set projection					
E.dRERE	violation of data integrity in EEPROM, error upon data storage	in case of recurring report send the instrument for repair					
E. 11E n.	EEPROM error	the "Def" values will be used in emergency, instrument needs to be sent for repair					
E.E.R.L 16	calibration error, loss of calibration data	instrument needs to be sent for repair					

# 10. INSTRUMENT DIMENSIONS AND INSTAL.


### Front view



### Panel cut




### Side view




Panel thickness: 0.5...20 mm

### Instrument installation

- 1. insert the instrument into the panel cut-out
- 2. fit both travellers on the box
- 3. press the travellers close to the panel





# Instrument disassembly

- 1. slide a screw driver under the traveller wing
- 2. turn the screw driver and remove the traveller
- 3. take the instrument out of the panel

# 11. TECHNICAL DATA

Selectable in configurations menu					Í.					
D4 V					PROJECTION					
O40 V	•				Bargraph					
O400 V		040 V 1 M0hm				1 " 0 " '				
Decimal point:   Decimal point:   BRIGHT:   Selectable in programming mode   BRIGHT:   Selectable in configurations menu   O2 V   1 MOhm   Input 1   O4 Ohm   Input 1   Input 1   O4 Ohm   Input 1   In										
D150 mV										
NSTRUMENT ACCURACY		060 mV 1 MOhm								
INSTRUMENT ACCURACY		0150 mV	1 MOhm	Input 1	BRIGHT.:	adjustable - in programming mode				
D400 mA		0300 mV	1 MOhm	Input 1						
O1 A										
Selectable in configuration menu   PM   O/420 mA   < 400 mV   Input I										
Selectable in configuration menu					Accuracy:					
Selectable in configurations menu		05 A	< 60 mV	Input 1						
O/420 mA	adamble to our	f:		DAI						
02 V   1 M0hm   Input U   1	selectable in con		~ 400V							
Commertion:		,	-,		Resolution:					
Selectable in configuration menu   O400 Ohm   O40										
Selectable in configuration menu  OHM  O400 Ohm O400 Ohm O40 Wohm O40 Work-hog: reset after 1,2 s calibration: at 25°C and 40 % r.h.  COMPARATOR  Type: digital, adjustable in the menu Limits: 9993999 Delay: O9993999 Delay: O9993999 Delay: O9993999 Delay: O999.s Outputs: 2x relays with switch-on contact (230 VAC/30 VDC, 3 A)** Relay: 1/8 HP 277 VAC, 1/10 HP 125 V, Pilot Duty D300  DATA OUTPUTS  Protocols: ASCII  DATA OUTPUTS Protocols: ASCII  Age: 150115 200 Baud No megalloy) O°1 760°C Rate: 150115 200 Baud No megalloy) O°										
Comp. of conduct:   Comp. of conduct:   Comp. of conduct:   Comp. of cold junct:   adjustable   T/C		U1U V	I MUNM	Input U						
0400 0hm	selectable in con	figurationm menu		ОНМ						
Connection:	30.00.000.00									
Connection:					Comp. of cold junct.:					
S105 Ohm		0 40 k0hm			F45					
Connection:   2 wire   Watch-dog: reset offer 1,2 s   Calibration: at 25°C and 40% r.h.					FUNCTIONS:	Hold - stop measuring (upon contact)				
Connection:         2 wire         Watch-dog: reset after 1, 2 s at 25°C and 40 % r.h.           Pt xxxx         -99,9°399,9°C           Ni xxxx         -30,0°250,0°C         COMPARATOR           Type Pt:         100/500/1 000 0hm, platinum couple s cx=0,003850hm/0hm/°C         Type:         digital, adjustable in the menu Limits: -9993999           Type Ni:         Ni 1 000/2 226/10 000, 5000 ppm/6180 ppm         T/C         Limits: -9993999           Connection:         2, 3 or 4 wire         0999         Delay: 0999           Connection:         1 (Fe-CuNi)         0°900°C         (230 VAC/30 VDC, 3 A)*           Relay:         1/8 HP 277 VAC, 1/10 HP 125 V, Pilot Duty D300           M (NiCr-Ni)         0°690°C         DATA OUTPUTS           F (NiCr-CuNi)         0°1 760°C         8 bit + no parity + 1 stop bit (ASCII)           Rate:         150115 200 Baud         RS 232: isolated, two-way communication, oddressing (max. 31 instruments)			(unon request)							
Pt xxxx	Connection:		(opon rodoosi)	por 2	w.ll	•				
Pt xxxx										
Ni xxxx				RTD	Calibration:	at 25°C and 40 % r.n.				
Ni xxxx	Pt xxxx	-99,9°399,9°C			COMPARATOR					
Type Pt:	Ni xxxx	-30,0°250,0°C				digital adjustable in the many				
Type Ni: Ni 1 000/2 226/10 000, 5000 ppm/6180 ppm   Connection: Q 2 3 or 4 wire   V   Connection: Q 3 or 4 wire   V   Conne	Type Pt:	100/500/1 000 0	hm, platinum couple		, , , , , , , , , , , , , , , , , , ,	0 , 1				
Type Ni: Ni 1 000/2 226/10 000, 5000 ppm/6180 ppm   Delay: 099,9 s		s $\alpha$ =0,003850hm	/0hm/°C							
Connection:   2, 3 or 4 wire   Selectable in configurations menu   T/C	Type Ni:	Ni 1 000/2 226/1	0 000, 5000 ppm/61	80 ppm	/	*****				
Selectable in configuration menu	Connection:				,					
Relay: 1/8 HP 277 VAC, 1/10 HP 125 V, Pilot Duty D300		·			outpuis.	,				
No.   No.		•		T/C	Polave					
T (Cu-CuNi) 0°400°C E (NiCr-CuNi) 0°690°C B (PiRh30-PiRh6) 300°1 820°C R (Pi13Rh-Pi) 0°1 760°C R (Pi13Rh-Pi) 0°1 740°C R (Pi13Rh-Pi) 0°1 300°C N (Omegalloy) 0°1 300°C - The instrument evaluates only temperatures higher	Туре:				Keluy.	1/0 HF 2// VAC, 1/10 HF 123 V, FII01 DUTY D300				
E (NiCr-CuNi) 0°690°C Protocols: ASCII  B (PrRh30-PrRh6) 300°1 820°C Data format: 8 bit + no parity + 1 stop bit (ASCII)  S (PrRh10-Pt) 0°1 760°C Rate: 150115 200 Baud  R (Pr13Rh-Pt) 0°1 740°C RS 232: isolated, two-way communication  N (Omegalloy) 0°1 300°C RS 485: isolated, two-way communication, addressing (max. 31 instruments)		, ,			DATA CHITPHITS					
B (PRR30-PRR6) 300°1 820°C		, ,				ACCII				
S (PiRh10-Pt) 0°1 760°C Rate: 150115 200 Baud R (Pr13Rh-Pt) 0°1 740°C RS 232: isolated, two-way communication N (Omegalloy) 0°1 300°C RS 485: isolated, two-way communication, - The instrument evaluates only temperatures higher										
R (P13Rh-P1) 0°1 740°C RS 232: isolated, two-way communication N (Omegalloy) 0°1 300°C RS 485: isolated, two-way communication, addressing (max. 31 instruments)										
N (Omegalloy) 0°1 300°C RS 485: isolated, two-way communication, - The instrument evaluates only temperatures higher addressing (max. 31 instruments)		, ,								
- The instrument evaluates only temperatures higher addressing (max. 31 instruments)										
- The instrument evaluates only temperatures inglier					K5 485:					
than the temperature of the cold junction (C JC)						adaressing (max. 31 instruments)				
		than the temperatu	re ot the cold junction	(C JC)						

DU

\* values apply for resistance load

Lin. pot.supply

2,5 VDC/6 mA

min. potentiometer resistance is 500 Ohm

#### ANALOG OUTPUTS

Type: isolated, programmable with resolution of max.

10 000 points, analog output corresponds with the displayed data, type and range are adjustable

PM

Non-linearity: 0,2% of the range

TC: 100 ppm/°C

Rate: response to change of value < 100 ms

Voltage: 0...2 V/5 V/10 V

Current: 0...5/20 mA/4...20 mA

- compensation of conduct up to 600 Ohm

EXCITATION

Adjustable: 2...24 VDC/50 mA, isolated

**POWER SUPPLY** 

Options: 24/110/230 VAC, 50/60 Hz, ±10 %, 5 VA

10...30 VDC/max. 300 mA, isolated by a fuse inside the instrument

Protection: by a fuse inside the instrument VAC (T 80 mA), VDC (T 630 mA)

**MECHANIC PROPERTIES** 

Material: Noryl GFN2 SE1, incombustible UL 94 V-I

Dimensions: 96 x 48 x 120 mm
Panel cut-out: 90.5 x 45 mm

**OPERATING CONDITIONS** 

Connection: connector terminal board,

conductor section up to 2,5 mm<sup>2</sup>
Stabilisation period: within 15 minutes after switch-on

Working temp.: 0°...60°C
Storage temp.: -10°...85°C

Cover: IP65 (front panel only)
Construction: safety class I

Overvoltage cat.: EN 61010-1, A2

III. - instrument power supply (300 V)
II. - input, output, excitation (300 V)

for pollution degree II

EMC: EN 61000-3-2+A12; EN 61000-4-2, 3, 4, 5, 8, 11;

EN 550222. A1. A2

# 12. DECLARATION OF CONFORMITY

Company: ORBIT MERRET, spol.s r.o. (Ltd.)

Klánova 81/141 142 00 Prague 4 Czech Republic

Manufactured: ORBIT MERRET, spol.s r.o. (Ltd.)

Vodňanská 675/30 198 00 Prague 9 Czech Republic

declares at its full responsibility that the product presented hereunder meets all technical requirements, is safe for use when utilised under the terms and conditions determined by ORBIT MERRET, spol.s r.o. and that our company has taken all measures to ensure conformity of all products of the type listed hereunder, which are being brought out to the market, with technical documentation and requirements of the appurtenant statutory orders.

Product: Programmable Bargraph

Type: OMB 301, in versions: DC, PM, DU, PWR, OHM, RTD, T/C

Mode of asses. of conformity: §12, par. 4 b, d of Act No.22/1997 Sb.

Conformity is assessed pursuant to the following standards::

Electrical safety: EN 61010-1

EMC: EN 50131-1, par. 14 and par. 15

EN 55022

EN 61000-3-2 + A12, Cor. 1, change A1, change A2

EN 61000-4-2 EN 61000-4-3 EN 61000-4-4 EN 61000-4-5 EN 61000-4-8 EN 61000-4-11

and government ordinance:

Electrical safety: No. 168/1997 Sb. EMC: No. 169/1997 Sb.

The evidence are the protocols of authorized and accredited organization:

VTÚE Praha, experimental laboratory No. 1158 accredited by ČIA, o.p.s. with EN ISO/IEC 17025

Place and date of issue: Prague, 21. november 2001 Miroslav Hackl

Company representative

# 13. CERTIFICATE OF GUARANTEE

Product	OMB 301	DC	PWR	PM	DU	RTD	T/C	ОНМ
Туре								
Manufacturing No.								
Date of sale			A					
A guarantee period of 24 mc Defects occuring during this charge.  For instrument quality, function	period due to m	anufactu n the gua	re error o	or due to	o mater	ial faults	shall be	
and used in compliance with	the instruction to	or use.						
- unavoidable	amage of unqualified pe	erson inc	l. the user					
The manufacturer performs th	e guarantee and	d post-gu	arantee r	epairs u	nless pr	ovided fo	r otherv	vise.
		Stamp	, signatur	e				

#### ORBIT MERRET, spol. s r.o.

Vodnanska 675/30 198 00 Prague 9 Czech Republic

tel: +420 - 281 040 200 fax: +420 - 281 040 299

e-mail: orbit@merret.cz www orbit merret cz

#### Austria

ING.E.GRUBER GmbH Edu. Kittenberger Gasse 97 Top2 A-1230 Wien tel: +43 - 1 - 869 23 39-0 fax: +43 - 1 - 865 18 75

e-mail: office@gruber-components.at www.gruber-components.at

#### The Netherlands

AE SENSORS B.V. J. Valsterwea 92 3301 AB Dordrecht tel: +31 - 78 - 621 31 52 fax: +31 - 78 - 621 31 46 e-mail: aesensors@aesensors.nl www.gesensors.nl

#### Slovakia

TECHREG, s.r.o. Dukelských hrdinov 2 984 22 Lučenec tel: +421 - 47 - 433 15 92 fax: +421 - 47 - 433 15 92 e-mail: techrea@bb.psg.sk www.techreg.sk

#### Ukraine

OOO <KOTRIS>

Nesterova 3, Office 907 030 57 Kyjev tel: +44 - 446 - 21 42 fax: +44 - 446 - 21 42

e-mail: metrix-ua@svitonline.com

#### Germany

MEGATRON Flektronik AG & Co. Hermann-Oberth-Str. 7 85640 Putzbrunn/München tel: +49 - 89 - 460 94 - 0 fax: +49 - 89 - 460 941 01 e-mail: sales@megatron.de www.megatron.de

#### Russian Federation

PO <INTERFACE> ab 3408 Krasnodar, 350044 tel: +1 - 8612 - 660 483 fax: +1 - 8612 - 623 000 e-mail: itf@au.ru www meter chat ru

#### Switzerland

Zürcherstrasse 137 8952 Schlieren tel: +41 - 1 - 730 27 53 fax: +41 - 1 - 730 27 83 e-mail: info@orbitcontrols.ch www.orbitcontrols.ch

ORBIT CONTROLS AG

#### USA

METRIX Instruments Co. 1711 Townhurst Dr Houston, Texas 77043-2899 tel: +1 - 713 - 461 21 31 fax: +1 - 713 - 461 82 83 e-mail: sales@metrix 1.com www.metrix1.com

#### Lithuania

RIFAS UAB Tinklu g. 29a LT-5300 Panevéžvs tel: +370 - 5 - 510 400 fax: +370 - 5 - 582 729 e-mail: sales@metrix1.com www.metrix1.com

#### Russian Federation ZAO <ROSPRIBOR>

Tamozhennyi proezd, dom 12, office 2-15 Moscow, 111033 tel: +1 - 95 - 36 29 446 fav: +1 - 95 - 36 29 177

e-mail: sales@rospribor.com www.rospribor.com

# Turkey

ALFA ELEKTRONIK Ltd. Baglarbasi Mah. Ergenekon No: 33 TR - 81540 Maltene - ISTANBUL tel: +90 - 216 - 442 39 49 fax: +90 - 219 - 305 54 50 e-mail: sh@elmak.com.tr www.alfa-technik.com